ARM Nauru Research Station

Site Visit 0708N Report

Visit Duration: 16 August to 30 August 2007

Nauru Island, Republic of Nauru

SV-0708N					
Final Report					
Site: Nauru Dates on Site: 16 - 30 August 2007					
Team Members: Troy Culgan Mike Ryczek	Required Items & Other Actions: • DC-to-DC converters (4 12V and 4 24V, ship from SGP) • Waterproof 110-V outlets - MA to purchase • New IRT PC and cables (on site) • RHE OS HDs (4) (on site) • Loggernet upgrade CD (on site) • MPL port window glass (on site) • CIMEL EPROM from SGP (on site) • MWR PC (ship from Darwin after config) • Nera SAT phone (ship from SGP week of 23Jul) • Anemometer w/ replacement cable (ship from Darwin) • Newly calibrated loggers (ship from Darwin) - TC • AED upgrade software (hand-carry from Darwin) • 6 12V Gell Cell Batteries for Instrument Field Power (on site) • AERI Scene Mirror (on site)				
Task Summary:	Safety: Major Hazards: Caustic chemicals (KOH), Explosive gas (H2), AC electricity Hazard Controls: BOM Electrolyser Handbook, BM Electrolyzer Operations/Maintenance Training, ASNZS 4836/2001-Safe Working on LV Electrical Installations, 2-man rule When replacing items (e.g., desiccant, filters, etc.), record and report the quantity of spares left on site.				
SITE TASKS					

High priority / usually non-routine

Low priority / usually routine

Completed

	High priority / u	h priority / usually non-routine		Low p	riority / usually routine	Completed
Priority	System	Date Completed (dd/Month)		vice Time (hours)	Tasks For each priority item insert new line (row) for each date/time entry	
1	BBSS				Replace DigiCORA II w/	new DigiCORA III
		18-Aug			Preparations for Digicora	
		19-Aug		4	Digicora III installed (BBS	,
1	BBSS				Train Observers on DigiO	
		19-Aug			•	ervers (Franklin given instruction)
		20-Aug			Robroy Whippy given ins	
		21-Aug		2	Equina & Andrew given i	
1	BBSS				Update DigiCORA III sof	
		18-Aug		1	Digicora III software updated to version 3.52.1	
1	BBSS				Update GC25 firmware	
		19-Aug		1	GC25 fimware updated to SW 3.020 (serial#A17105) & (serial #	
					A12426, spare)	
2	SMET				Check lower anemometer for alignment - needs replacing	
		20-Aug			Lower anemometer replaced. Anemometer serial# 73681/08234	
					installed. Instrument replacement form sent.	
3	MWR				Install new PC	
		21-Aug		1	MWR GX 270 (serial number JGW9Q41) replaced with GX620	
					computer property tag 1153921 (serial number 76RC881)	
4	IRT				Install new IRT PC and data cable (IRT PC and cable to ship from	
		00.4			SGP) - LJ to ask Morris	
		23-Aug		4	In Progress, require the following information from mentor: IRT	
					computer IP address, IRT configuration, 7) start IRT data	
					acquisition program	
					What is the login/password to log into IRT computer?	
					What is the data acqusition program and how do we start it?	

	SITE TASKS						
	High priority / u	High priority / usually non-routine		riority / usually routine Completed			
Priority	System	Date Completed (dd/Month)	Service Time (hours)	Tasks For each priority item insert new line (row) for each date/time entry			
		24-Aug	2	IRT computer installed, serial connection to IRT computer installed. IRT serial communication set at 19.2K N-8-1,Trig=on,sample rate set to 0.1 sec			
5	IRT			Change IRT emissivity value from 1.000 to 0.987 (per BCR 1384)			
		17-Aug	0.5	Emissivity value change to 0.987 per BCR1384 at 23:30, 16Aug07 utc			
6	IRT (SKY)			Install new IRT ventilated enclosure			
				Not required this site visit			
7	AERI			Install Scene Mirror			
		18-Aug	1	AERI scene mirror replaced			
8	DS			Change out R1 PC			
		19-Aug	0.5	Facility Contact WorkSheet (CS-2007-0369) Facility Contacted: Nauru			
				Contact Date: 10-May-2007 Contact Time: 03:25:00 UTC			
				Contact Sheet Initiator: Culgan, Troy Person or System Contacted: Teimitsi, Franklin			
				System(s) Related to Contact: OTHER Contact Subject/Keywords: R1- hardware replacement			
				Contact Details: Ron Reed requested that I work with the Nauru observers to replace the failing hardware of the R1 computer. Hard drive was removed from current R1 computer and put into a spare GX620. Awaiting Ron to verify R1 operability. Observers involved Franklin and Rb Roy.			
9	DS			Install 4 upgrade RHE OS HDs (per BCR 01142)			
		21-Aug	2	Installed RHE OS HD's. Worked with Matt McDuff to restore connectivity to NFS and Collector			
10	CIMEL	<u>.</u> .		Install new CIMEL EPROM			
<u> </u>		22-Aug		Request Wayne Newcomb confirm to perform change.			
		23-Aug 30-Aug		EPROM change performed at 22:00 22 Aug07 utc Repair serial communication cable, evidence it had been chewed			
11	HVAC			Perform HVAC repair - Culgan to check w/ Andrew K.			
		21-Aug	6	Mike replaced HVAC#1 in E-Van			
12	HVAC	21 / tag	J	Train local electrician (William)			
		21-Aug		Not required			
13	HVAC	217.009		Pressure-wash outdoor condenser coil			
		24-Aug	2	Completed			
14	ES&H	2 + 7 tag		Update AED software			
17	20011	17-Aug	0.5	AED software updated			
15	ES&H	17-Aug	0.5	Restock first-aid kit on site			
10	LOGIT	25-Aug	0.5	Personal First Aid kit on site is stocked, recommend sending a replacement Industrial First Aid Kit			
16	GENSET			Verify correct operation of Genset exerciser card; check time settings; replace timer battery			

	SITE TASKS						
	High priority / u	igh priority / usually non-routine Low p		riority / usually routine	Completed		
Priority	System	Date Completed (dd/Month)	Service Time (hours)	Tasks For each priority item insert new line (row) for each date/time entry			
		17-Aug	1	Battery changed, exerciser timer po at 11:00 Wednesday Nauru local ti		test	
17	GENSET			Change oil, oil filter, fuel filter, Raccanalysis - work w/ local GENSET to	or filter; Take SOS to Darwin	n for	
		24-Aug	1	Oil purchased			
		28-Aug	4	Genset maintenance complete			
18	LGR			Loggernet upgrade using CD sent			
		22-Aug		Awaiting administrator user name 8 address can be set on computer	•		
		23-Aug	1	Installed during loggernet compute	r change to GX620 with core	ерс	
19	OTHER			Mark up site plans for CAD update			
		29-Aug	4	checked drawings provided for acc			
20	OTHER			Locate old PNNL NIES IBM 600E I	aptop (WD23534) - destroy l	HD	
		21-Aug	1	Not on site			
21	OTHER			Locate old PNNL NIES IBM 380XD	laptop (WD22312) - destroy	У	
				HD			
		21-Aug	1	Not on site			
22	OTHER			Remove PII from Observer PC (and record SN) as per procedure			
		25-Aug	1	PII removed from Observer PC property tag 1144280, observers instructed about procedure			
23	OTHER			Remove PII from Kaierua PC (and record SN) as per procedure			
		25-Aug	1	PII removed from spare observer PC Dell GX270 serial number 3L5ML51			
24	MPL			Check MPL port window			
		18-Aug	0.5	MPL window checked and cleaned; condition OK			
25	COMM			Check SAT phone extension from I			
		20-Aug	2	Sat phone operation D-Van to E-Va	an verified operational		
	00141			E-Van Number 872-76-322-2790			
26	COMM			Program SAT phone to allow dialing in on weekly Ops teleconference			
		18-Aug	0.5	Ops teleconference number progra	mmed to NERA Satphone		
27	LGR			Modify DC power supply to loggers	(pending BCR 615)		
				Not yet shipped			
28	LGR			Logger change out w/ newly calibra			
		18-Aug	2	SMET,SKYRAD & GNDRAD loggers changed out, instrument			
- 00	CONTRA			replacement forms sent			
29	COMM	04 4		Check Iridium SAT phone			
30	OTHER	21-Aug		Checked operational	all GY620s (CEII I aggaract	t	
30	OTHER			Replace instrument PCs w/ new De TSI, MWR, MPL, SAM, BBSS)	eli GA0205 (CEIL, Loggernei	ι,	
		19-Aug	2	Prepared GX620's for ceilometer a	nd MWR change out		
		20-Aug		Ceilometer GX 270 (WD45418) rep		r	
		_5 , .ag	·	property tag 1153919 (serial number J3RC881)			
		21-Aug	1	MWR GX 270 (serial number JGW9Q41) replaced with GX620			
				computer property tag 1153921 (serial number 76RC881)			

	SITE TASKS						
	High priority / u	sually non-routine	Low p	riority / usually routine Completed			
Priority	System	Date Completed (dd/Month)	Service Time (hours)	Tasks For each priority item insert new line (row) for each date/time entry			
		24-Aug	1	Loggernet GX 270property Tag WD42291 (serial number J5SYH31) replaced with GX620 computer property tag 1153917 (serial number 44RC881)			
31	WND			Replace anemometer cable w/ standard cable to establish consistency across all sites			
		25-Aug		Cable not yet shipped			
32	WND			Inspect anemometer surge protection			
0.0	071150	20-Aug	0.5	Surge protection inspected.Ok			
33	OTHER			Review fiber optic cables and determine spares needed in pre- terminated lengths			
		25-Aug	2	Review report sent to L.Jones and K.Nitschke			
33A	OTHER	05.4		Prepare report on Van floor degradation			
0.4	DWD	25-Aug	2	Review report sent to L.Jones and K.Nitschke			
34	PWR			Change out 6 12V Gell Cell Batteries for Instrument Field Power			
		23-Aug	2	Changed out 6 of 8 batteries			
35	LICOR			Troubleshoot			
		21-Aug		Awaiting response from Chuck Long			
		22-Aug	1	Chuck Long unable to assist, received a possible useful program			
		07.4	4	file for logger, sent file to Chuck Long to verify.			
		27-Aug		Uploaded program file to data logger wil retrieve data in two days time			
		30-Aug	1	Chuck Long reported that retrieved data is OK.			
36	GENSET			Check generator operation - it runs approx. 30 min/day w/o power outage			
		17-Aug		under test			
		18-Aug		Generator did not run w/o power outage			
		22-Aug		30min/day run problem rectified			
37	COMM			Verify dial-out procedure			
		18-Aug		Verified VOIP connection to US outside line			
		19-Aug	2	Install new phone in E-Van connected VOIP and satphone to phone			
38	OTHER			Replace 9V Battery in Automatic Transfer Switch Exercise Module			
		17-Aug	0.5	Battery replaced			
39	VANS			Evaluate need to replace roll around stairs to access top of vans			
				(old stairs were disposed of because of rust)			
		24-Aug	1	Information in reference to current site status sent to L.Jones			
39A	H2Gen			Electrolyser & RBL Maintenance			
		26-Aug		Electrolyser Maintenance progressing			
200	ANAC	27-Aug	6	Electrolyser and RBL maintenance complete			
39B	AWS	07 4	0	Troubleshoot humidity fault			
		27-Aug	2	Replaced humidity probe with spare that arrived, fault became intermittent, further investigation found a corroded pin#2, replaced using an unused pin of connector. Connector to be replaced next site visit.			
40	HVAC			HVAC routine maintenance			
		23-Aug	1	Completed			
41	OTHER			Perform routine maintenance tasks as per Maintenance Checklist			
				In progress			

	SITE TASKS						
	High priority / u	sually non-routine	Low p	riority / usually routine	Completed		
Priority	System	Date Completed (dd/Month)	Service Time (hours)	For each priority item ir	Tasks nsert new line (row) for each date/time entry		
		29-Aug		Routine maintenance tas	ks completed		
42	OTHER			Check ARM Kiosk			
		30-Aug		OK			
	SHIPPING			List items to be shipped following visit			
				Ship a spare GC25 to Manus			
				Ship old AERI scene mirror			
				Anemometer serial# 18426/72577			
				OLD Data system Hard Drives			
	FUTURE NEEDS			List items needed for future visits (spares, etc.)			
				Cat 5 cable			
				Cat 5 crimp kit			
				Lan cable test unit			
				Molecular Sieve dessicant for GC25			
				Single phase power cable			
				Air Filter membrane for MMCR Receiver/Modulator			
				Epoxy Resin to seal fibreglass stands and enclosures			
				Industrial First Aid kit			